

**CITY OF OJAI URBAN WATERSHED
ASSESSMENT AND RESTORATION PLAN**
(CDFG CONTRACT NO. PO250014)



Prepared for:
CITY OF OJAI

and

CALIFORNIA DEPARTMENT OF FISH AND GAME

With Assistance from:
HAWKS & ASSOCIATES

DMEC Mission Statement:

*To provide quality environmental consulting services with integrity
that protect and enhance the human and natural environment.*

August 2005



**City of Ojai Urban Watershed
Assessment and Restoration Plan**
(CDFG Contract No. PO250014)

Prepared for:

City of Ojai
401 South Ventura Street
Ojai, California 93023

and

California Department of Fish and Game
1807 13th Street, Suite 104
Sacramento, California 95814

Prepared by:

David Magney Environmental Consulting
P.O. Box 1346
Ojai, California 93024-1346

With Assistance from:

Hawks & Associates
2259 Portola Road, Suite B
Ventura, California 93003

8 August 2005

This document should be cited as:

David Magney Environmental Consulting. 2005. City of Ojai Urban Watershed Assessment and Restoration Plan (CDFG Contract No. PO250014). 8 August 2005. (PN 02-0151.) Ojai, California. Prepared for the City of Ojai, California, and California Department of Fish and Game, Sacramento, California.

Cover Photograph:

San Antonio Creek (Reach 1) along Creek Road near its confluence with Del Norte Creek (photograph taken on 3 December 2004).

TABLE OF CONTENTS

	PAGE
EXECUTIVE SUMMARY	1
INTRODUCTION.....	2
BACKGROUND	2
PROJECT OBJECTIVES	3
SOUTHERN STEELHEAD	4
STATUS AND DISTRIBUTION	4
LIFE HISTORY	5
SOUTHERN CALIFORNIA STOCK.....	6
THE VENTURA RIVER.....	7
RIVERINE WETLAND FUNCTIONS.....	8
PROJECT AREA.....	11
CITY OF OJAI HISTORICAL CONDITIONS	13
OJAI VALLEY AND CITY STREAMS	13
METHODS	18
STREAM HABITAT CHARACTERIZATION	18
WATER QUALITY SAMPLING	21
DETERMINING LIMITING FACTORS.....	22
EXISTING CONDITIONS	25
PHYSICAL ENVIRONMENT OF OJAI BASIN STREAMS	25
CLIMATE AND RAINFALL	25
HYDROLOGY	26
Subwatersheds.....	26
HABITAT CHARACTERIZATION OF STREAM REACHES	31
General Flow Conditions.....	31
Channel Morphology.....	33
Stream Type	34
Inundation.....	36
Water Depth and Width.....	37
Velocity and Discharge	38
Instream Description and Cover Type.....	40
Riparian Habitat	41
Percent Shading.....	42
Substrate Composition and Particle Size.....	45
Potential for Spawning and Rearing.....	48
WATER QUALITY.....	48
Conductivity and Specific Conductance	54
Temperature.....	55
Dissolved Oxygen and Carbon Dioxide	57
Turbidity.....	58
pH.....	60

TABLE OF CONTENTS (continued)

Salinity	62
Total Coliform Bacteria.....	63
BIOLOGICAL ENVIRONMENT OF OJAI BASIN STREAMS.....	68
PREDOMINANT PLANT SPECIES	68
HABITAT DESCRIPTIONS.....	68
Palustrine System (Riparian Habitats).....	73
Riverine System (Aquatic Habitats).....	82
WILDLIFE.....	84
Fauna	85
Wildlife Survey Results.....	85
Wildlife Habitats	90
ADJACENT LAND USES	94
LOCATION, QUANTIFICATION, AND ASSESSMENT OF SPECIFIC LAND-USE	
ACTIVITIES OF CONCERN	97
IMPERVIOUS COVER.....	100
QUANTIFYING IMPERVIOUS COVER	103
CLASSIFYING URBAN STREAM QUALITY POTENTIAL.....	104
Land Impervious Cover.....	104
Instream Impervious Cover	105
BARRIERS/FACTORS CAUSING HABITAT DEGRADATION	111
SAN ANTONIO CREEK WATERSHED MODIFICATIONS	111
Channelized Streams	113
Undergrounded Streams	115
Bridges, Culverts, and Other Barriers	117
SUMMARY OF OJAI CREEK CONDITIONS.....	121
ARBOLADA CREEK	121
AYERS CREEK	124
DEL NORTE CREEK	125
EAST END CREEK	126
FOX CANYON BARRANCA	126
GRANDVIEW-PARK DRAIN	128
NORDHOFF DRAIN	128
OAK CREEK.....	129
OJAI CREEK.....	130
POST OFFICE CREEK.....	131
SAN ANTONIO CREEK	131
SOULE PARK CREEK & WEST SOULE PARK CREEK	132
STEWART CANYON CREEK	133
THACHER CREEK	134
VILLANOVA CREEK.....	135
RESTORATION PLAN.....	136
CDFG’S FOCUS ON RESTORATION.....	136
OJAI BASIN STREAMS RESTORATION OPPORTUNITIES.....	137
RESTORATION GOALS AND PROJECTS.....	138

TABLE OF CONTENTS (continued)

Goal A - Remove Fish Migration Barriers	139
Goal B - Improve Aquatic Habitat Conditions.....	144
Goal C - Preserve Existing Riparian and Instream Habitats	149
Goal D - Prevent Aquatic Habitat and Water Quality Degradation	151
CONCLUSIONS	157
CITATIONS	158
REFERENCES CITED.....	158
PERSONAL COMMUNICATIONS.....	161
ACKNOWLEDGEMENTS	162
APPENDICES	163
APPENDIX A. FIELD DATA SHEETS.....	163
APPENDIX B. OJAI STREAMS WATER QUALITY SAMPLING RESULTS	163
APPENDIX C. SUMMARY TABLE OF CREEK OBSTRUCTIONS	163
APPENDIX D. SMALL SCALE TOPO MAPS OF OJAI STREAM DRAINAGES ...	163

LIST OF FIGURES

FIGURE	PAGE
1. Project Location Map.....	11
2. Aerial Photograph with Delineated Ojai Valley Streams	12
3. Ojai Basin Subwatersheds.....	16
4. Ojai City Streams.....	17
5. Map of Water Quality Sampling Stations in Ojai	20
6. Ojai Basin Subwatershed Areas.....	29
7. Delineation of Ojai City Stream Reaches	32
8. Scatter Plot of Conductivity Results for the Ojai Streams	55
9. Scatter Plot of Temperature Results for the Ojai Streams	56
10. Scatter Plot of Dissolved Oxygen Results for the Ojai Streams	58
11. Scatter Plot of Turbidity Results for the Ojai Streams.....	60
12. Scatter Plot of pH Results for the Ojai Streams.....	61
13. Scatter Plot of Salinity Results for the Ojai Streams	63
14. Current and Planned Land Uses	95
15. Map of Vacant Lots in Ojai	98
16. Map of Restaurants, Automotive Facilities, and Corporate Yards	99
17. Map of Ojai Roads	101
18. Map of Impervious Cover Levels for the Ojai Valley Subwatersheds	106
19. Map of Ojai City Streams Imperviousness	110
20. Major Modifications to the Streams of Ojai	112
21. Ojai City Streams Aboveground and Underground Channelization	114
22. Map of Ojai City Non-road Culverts	116
23. Map of Ojai City Bridges and Road Crossing Culverts	118
24. Map of Other Barriers in the City of Ojai	120
25. Map of Ojai Stream Reaches with Invasive Exotic Plants	145
26. Map of Potential Preserve Parcels	152

LIST OF TABLES

TABLE	PAGE
1. Ecosystem Functions of Riverine Wetlands	10
2. Subwatersheds Studied for the Ojai Streams Assessment	14
3. Creeks Studied for the Ojai Streams Assessment	15
4. Stream Habitat Characterization Field Survey Summary	19
5. Ojai Basin Streams Water Quality Sampling Sites	23
6. Summary of Ojai Basin Streams Hydrology	27
7. Area of Subwatersheds Upstream from the City of Ojai	28
8. Area of Subwatersheds in the City of Ojai	28
9. Length of Creeks and their Tributaries Upstream from Ojai City Limits	30
10. Length of Creeks and their Tributaries within the City of Ojai	30
11. Stream Characterization Results for Flows, Morphology, and Stream Type	35
12. Stream Characterization Results for Inundation, Water Depth and Width, Velocity, Discharge, and Stream Type	39
13. Stream Characterization Results for Instream, Habitat, and Shading	43
14. Stream Characterization Results for Substrate Composition and Particle Size	46
15. Stream Characterization Results for Spawning and Rearing Potential	49
16. Ojai Stream Reaches with Corresponding Water Quality Sampling Stations	51
17A. Summary of the Ojai Basin Streams Water Quality Sampling Results (Stations 1 through 9)	52
17B. Summary of the Ojai Basin Streams Water Quality Sampling Results (Stations 10 through 18)	53
18. Classes of Fresh Water Quality Standards	65
19. Federal Standards for Indicator Bacteria	66
20. Predominant Plant Species of the Ojai Basin Streams	69
21. Plant Communities Observed within the Ojai Streams	72
22. Wildlife Species of the City of Ojai and Ojai Basin Streams	86
23. Summary of Wildlife Surveys Conducted in the Ojai Streams	89
24. Land Use/Impervious Cover Relationships for Suburban Areas of Chesapeake Bay	103
25. Results of Land Impervious Cover Analysis for the Ojai Valley Watershed	105
26. Impervious Cover Lengths Summary for Creeks within the City of Ojai	107
27. Percent Impervious Cover Summary for Creeks within the City of Ojai	107
28. Summary of Stream Reach Imperviousness for Creeks of the City of Ojai	108
29. Undergrounded Streams Summary for Creeks within the City of Ojai	117
30. Summary of Favorable Conditions for Determining Spawning and Rearing Potential in the Ojai Creeks	122
31. Matrix of Potential Stream Habitat Restoration Actions by the City of Ojai	140

LIST OF PHOTOGRAPHS

PHOTOGRAPH	PAGE
1. Overflow of Thacher Creek on Ojai Avenue during winter storm event.....	25
2. San Antonio Creek during winter storm event.....	25
3. San Antonio Creek above Grand Avenue showing natural channel morphology.....	33
4. San Antonio Creek showing a rifle-pool-riffle stream type.....	34
5. San Antonio Creek showing a run stream type.....	34
6. Stewart Canyon Creek showing root wads and logs as functional instream cover.....	41
7. San Antonio Creek showing quality functional riparian habitat.....	42
8. Fox Canyon Barranca showing poor quality stream habitat predominated by invasive exotics.....	42
9. Boulders of San Antonio Creek.....	45
10. Cobbles of Fox Canyon Barranca.....	45
11. Gravels of Arbolada Creek.....	45
12. Freshly painted “Don’t Dump” sign on Daly Road.....	50
13. Thacher Creek during winter storm creating elevated levels of turbidity.....	59
14. “Don’t Litter” sign on fence of Fox Canyon Barranca at Ojai Avenue.....	64
15. Close proximity of horse corral to active creek channel.....	64
16. Positive coliform indicator results for Water Quality Sampling Stations 1 through 5.....	67
17. Positive coliform indicator results for Water Quality Sampling Stations 6 through 10.....	67
18. Positive coliform indicator results for Water Quality Sampling Stations 11, 12, 14, 15, & 17.....	67
19. Fox Canyon Barranca, Mugwort (<i>Artemisia douglasiana</i>) in foreground.....	68
20. Ojai Creek, California Wild Grape (<i>Vitis californica</i>) climbing sycamores and oaks.....	68
21. Post Office Creek, Pacific Blackberry (<i>Rubus ursinus</i>) creating the groundcover.....	68
22. Del Norte Creek, view north showing Cattail Series in the foreground.....	73
23. Nordhoff Drain showing California Annual Grassland.....	74
24. Grandview-Park Drain showing Ruderal Grassland Series.....	75
25. San Antonio Creek showing old-growth Arroyo Willow Series.....	76
26. Fox Canyon Barranca showing Mulefat Series.....	77
27. Fox Canyon Barranca showing California Sycamore Series.....	80
28. Upper end of Stewart Canyon Creek showing dense Coast Live Oak Series.....	81
29. Lower end of Stewart Canyon Creek showing intermittent canopy of Coast Live Oak Series.....	81
30. Nordhoff Drain and Happy Valley Drain confluence showing dense Eucalyptus Series.....	82
31. Arbolada Creek showing how very little grows beneath Eucalyptus Series.....	82
32. Arbolada Creek view north showing planted ornamentals prohibiting natives establishment.....	82
33. Fox Canyon Barranca showing dominance by escaped ornamentals.....	82
34. Matilija Shoulderband Snail (<i>Helminthoglypta willetti</i>).....	85
35. Black-bellied Slender Salamander.....	85
36. Spiders.....	85
37. Beetle larvae.....	85
38. Grandview-Park Drain showing Raccoon and bird tracks in the Riverine habitat.....	93
39. Stewart Canyon Creek Reach 1 showing root wads under which a Steelhead was observed.....	93
40. Stewart Canyon Creek showing a Mallard foraging in the stream channel.....	93
41. Horse corral next to channel.....	96
42. Horse urine and manure within 25 feet of creek.....	96
43. Lower open portion of Stewart Canyon Creek flood channel.....	96
44. Fire fighting activities that damaged aquatic habitats on San Antonio Creek.....	96
45. Undersized culvert for driveway entrance along Signal Street.....	96
46. Stewart Canyon Creek showing example of natural surface.....	109
47. Ojai Creek showing example of compacted surface.....	109

LIST OF PHOTOGRAPHS (CONTINUED)

48. Stewart Canyon Creek showing example of impervious surface	111
49. Stewart Canyon Debris Basin empty during spring and summer months	113
50. Stewart Canyon Debris Basin filled after winter storm event	113
51. San Antonio Creek Arizona Crossing at Soule Park Golf Course as major Steelhead barrier	113
52. San Antonio Creek Arizona Crossing at Soule Park Golf Course washed out and buried	113
53. Stewart Canyon Creek showing aboveground flood control concrete channel	115
54. Fox Canyon Barranca showing meander pattern in concrete channel	115
55. Undergrounding of Ojai Creek	115
56. Undergrounding of Stewart Canyon Creek by a flood control channel and box culvert	115
57. Fox Canyon Barranca bridge with box culvert	117
58. Fox Canyon Barranca bridge with cement floor at North Ventura	117
59. Fox Canyon Barranca underground intake (non-road) culvert, view downstream	119
60. Grandview-Park Drain road culvert	119
61. Fox Canyon Barranca Debris Dam	119
62. Stewart Canyon Creek Debris Basin with standpipe	119
63. Arbolada Creek Reach 1	124
64. Arbolada Creek Reach 2, view north	124
65. Ayers Creek	125
66. Ayers Creek	125
67. Del Norte Creek view north	126
68. Del Norte Creek view south	126
69. Fox Canyon Barranca Reach 1	127
70. Fox Canyon Barranca	127
71. Grandview-Park Drain	128
72. Grandview-Park Drain	128
73. Confluence of Happy Valley Drain and Nordhoff Drain, view northeast	129
74. Oak Creek view upstream, at the end of San Antonio Street	129
75. Oak Creek view downstream, at the end of San Antonio Street	129
76. Ojai Creek showing channelization along Signal Street, view south	130
77. Ojai Creek at Lion Street, high flows during winter storm event	130
78. Post Office Creek	131
79. Confluence of Ojai and Post Office Creeks	131
80. San Antonio Creek showing high-quality riparian/aquatic habitat with summer flows	132
81. San Antonio Creek with peak flows during winter storm	132
82. Stewart Canyon Creek Reach 1 with functional riparian habitat	134
83. Stewart Canyon Creek's channelized Reach 4; peak flows during winter storm, view north	134
84. Thacher Creek	134
85. Thacher Creek	134
86. Villanova Creek (lower end) along Ojai Bike Path	135
87. Villanova Creek (upper end) along Ojai Bike Path	135
88. Stewart Canyon Debris Dam Spillway	142
89. Mexican Fan Palm Invading Oak Creek	146
90. Trash in Grandview-Park Drain	146
91. Foreign material in Ayers Creek	146
92. Fecal material source contaminating active creek	148
93. Unvegetated and compacted channel of Ojai Creek	148
94. Del Norte Creek at Ojai Valley Inn Golf Course lacking any buffer.....	149
95. Native plants used in Cluff Vista Park	154